



WASHINGTON STATE DEPARTMENT OF
Natural Resources
Peter Goldmark - Commissioner of Public Lands

Application for Use of State-owned Aquatic Lands

Applicant Name: Tom & Peggy Phillips
County: San Juan County
Water Body: East Sound
Type of Authorization - Use: License – Mooring Buoy
Authorization Number: 23-088594
Term: 5 years

Description: This agreement will allow the use of State-owned aquatic lands for the sole purpose of a recreational use Mooring Buoy. It is located in East Sound, in San Juan County, Washington.

Posted on 4/3/2012



WASHINGTON STATE DEPARTMENT OF
Natural Resources
 Peter Goldmark - Commissioner of Public Lands

MOORING BUOY/BOATLIFT LICENSE APPLICATION

Upon receipt of this application for placing a mooring buoy or boatlift on state-owned aquatic land, the Washington State Department of Natural Resources (DNR) will review it and notify you in writing if the application is accepted for further review. DNR may reject this application at any time before authorization.

There are three ways DNR authorizes mooring buoys. A mooring buoy application is needed for each, regardless of type.

- A **registration** is for abutting owners of residential waterfront property that meet the requirements of the brochure. If you follow the guidelines in this application, it serves as your registration and is valid for 5 years. *(No application fee is required).*
- A **license** is appropriate for all other mooring buoy holders (i.e. non-commercial and non-residential property owners). Your mooring buoy license is valid for 5 years. *Enclose a \$25.00 non-refundable application-processing fee with the application.*
- A **lease** is appropriate if you are considering a commercial use of the buoy such as for a business related activity or subleasing the buoy to another person. Mooring buoy leases are valid for up to 12 years. *Enclose a \$25.00 non-refundable application-processing fee with the application.*

There is one way DNR authorizes boatlifts. If you follow the guidelines in this application, it serves as your license application.

- A **license** is appropriate for all other mooring buoy holders or boatlift applicants (i.e. non-commercial and non-residential property owners). *Enclose a \$25.00 non-refundable application-processing fee with the application.*

Any agency, political subdivision or municipal corporation of this state, or the United States is exempt from this \$25.00 application fee (WAC 332-10-190).

Department of Natural Resources -OR Orca Straits District Aquatic Region 919 N Township Street Sedro-Woolley, WA 98284-9384 360-856-3500	Department of Natural Resources -OR Shoreline District Aquatic Region 950 Farman Avenue N Enumclaw, WA 98022-9282 360-825-1631	Department of Natural Resources -OR Rivers District Aquatic Region 601 Bond Road; PO Box 280 Castle Rock, WA 98611-0280 360-577-2025
----------------------------------------------------------------------------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------------------------------------------------------------------------------

1. Name: Tom & Peggy Phillips Date: 7-18-11
 Address: 8061 Lakemont Dr NE
 City: Seattle State: WA Zip: 98115-5235
 Phone Number: Home: 206-729-0343 Work: 206-355-6389
 E-mail Address: peggyrphillips@comcast.net

2. Which of the following applies to Applicant (check one):
 Washington corporation Partnership Marital Community Single Individual - OR
 (Other - please explain)

3. Check if Upland Parcel owner address is the same as above. If not, fill in below:

Upland Parcel Owner Name: Tom & Peggy Phillips

Address: 371 E Young Rd

City: Olga

State: WA Zip: 98279

Phone Number: Home: 360-376-4902 Work:

E-mail Address: peggyvphilips@comcast.net

List or attach the required information for buoy/boatlift location:

4. Legal Description: County Tax Parcel Number 1609-51005

Government Lot(s) 5 in Section 9 Township 36 N. Range 1 W East-West W.M.

5. Latitude: N 48° 37.002 Longitude: W 122° 49.947 48.616791 -122.832488

6. Global Positioning System (GPS) location if known: N 48° 37.002 W 122° 49.947

7. Depth of Water at buoy / boatlift location: 24' MLLW

8. Length of Vessel: no vessel at this time Vessel Registration Number: N/A

9. Attach copies of any regulatory permits or waivers required. Although this may not be a complete list for your area, note the ones needed and attached:

Not required mooring older than 2 yrs.

a. WA Department of Fish & Wildlife

b. County Shoreline Permit (s) - PSJXMP-IL-0041

c. U.S. Army Corp of Engineers NWS-2012-46

d. WA Department of Ecology

e. Other

account 002176
Phillips

Land Manager:	<u>New Application</u>	Renewal Application
Land Manager: Initials	1051112	Aquatic Program Manager Initials
Support: Application Fee Received	3/22/2012	Date 2946
Land Records: New Application Number		
Land Records: Trust	County	AQR Plate No.

INFORMATION REQUIREMENTS FOR A MOORING BUOY/BOATLIFT LICENSE APPLICATION

With your application, include all of the following:

Submit EXHIBIT A: two pages of maps no larger than 18 inches x 24 inches.

On the first page: A vicinity map on a USGS 7.5 minute quadrangle map.

On the second page: A drawing (that provides the details for question 5, below) at a scale of 1 inch = 200 feet or larger.

1. Is there a mooring buoy or boatlift currently at this site? Yes No
2. If yes, does the mooring buoy or boatlift belong to the applicant? Yes No

If no, please provide owner information:

Name:

Address:

City:

State:

Zip:

Phone Number: Home:

Work:

E-mail Address:

3. If yes, is the mooring buoy or boatlift authorized by DNR? Yes No I don't know
4. If yes, what is the DNR lease or authorization number?

5. On Exhibit A drawing, mark the position of the buoy or boatlift, acquired either by a differentially corrected Global Positioning System (GPS) measurement or by conventional surveying methods. Mark the position in relation to its anchor. The information must be accurate to (+ or -) 10 feet. A licensed surveyor must provide this information, or you must document it as follows:

- A. List the anchor position coordinate, with a state plane grid coordinate or a latitude and longitude. N 48° 37.00
W 122° 49.90
- B. Detail the survey method used to mark the position of the buoy or boatlift. Differentially corrected GPS
- C. List the land stations used to fix the position. You must have a minimum of two fixed stations and a closed traverse, or differentially corrected GPS measurements to determine the (+ or -) 10 feet requirement, and verify azimuth.
- D. List the date and time you performed the work. Sept. 6, 2011 at 10:30 am
- E. List the tidal correction and the depth to the anchor of the buoy or boatlift, and how you determined it.
- F. Provide the distance from the appropriate line of state ownership—for example, mean high tide, extreme low tide, the line of ordinary high water, or the line of navigability (fresh water).
- G. List the distance from other mooring anchors, structures or hazards in the area.
- H. Show a full circle on the exhibit that should be free from all obstacles including buoys, docks or other hazards.

E. Mooring rode is 1" L AT High tide. Mooring set in 25' water at MLW. with 35' of rode. Determined when servicing the mooring


F. The distance from shore at:
Mean High Tide = 530' EXTREME LOW TIDE = 490'

Ordinary High Water = 519'

MAINTENANCE PLAN

Describe in detail the maintenance plan for the buoy and / or boatlift and anchoring system:

The mooring is on an annual maintenance servicing schedule. The service is performed at a minus tide where as it is easy to get to the top end of the mooring. The top end is the part that would need replacing because it is a galvanized shackle and galvanized $\frac{1}{2}$ " cargo link chain. The rest of the mooring parts do not need servicing because they are plastic, nylon, stainless steel and concrete. Therefore the mooring does not disturb the substrate after it is installed.




Phillips Buoy



1:4800

This data has been compiled for San Juan County. Various official and unofficial sources were used to gather this information. Every effort was made to ensure the accuracy of this data, however, no guarantee is given or implied as to the accuracy of said data.



VICINITY MAP

Map Report: 04/05/2006

Map Legend:

- | | | | |
|---------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------|
|  Parcels |  Roads |  Parcel Numbers |  Road Names |
|  Addresses |  Lakes |  Wetlands |  Contour Lines |



Neither San Juan County nor the Assessor warrants the accuracy, reliability or timeliness of any information provided. Any person or entity who relies on information obtained from this real property query does so at his or her own risk.

EXHIBIT A